

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |  |      |             |
|-----------------------|--|------|-------------|
| CAMPAIGN No.          | 4017   | DATE | Mar.30.2017 |
| MANUFACTURER          | TOYOTA   |      |             |
| DESCRIPTION OF DEFECT | In the driver side frontal airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated. |      |             |

| TYPE                  | COMMERCIAL NAME    | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------------------|--------------------|---------------------|-------------------|
| UA-NCP10<br>CBA-NCP10 | [Vitz]             | 2002-2004           | 986               |
| UA-NCP13<br>CBA-NCP13 |                    |                     | 1,824             |
| UA-NCP15              |                    | 2002-2003           | 3,798             |
| UA-SCP10              |                    | 2002-2004           | 8,847             |
|                       |                    | 2002-2003           | 540               |
| UA-SCP13<br>CBA-SCP13 |                    | 2002-2004           | 11,355            |
| UA-ACA20W             | [RAV4J]<br>[RAV4L] | 2003                | 2                 |
| UA-ACA21W             |                    |                     | 69                |
| UA-ZCA25W             |                    |                     | 2                 |
| UA-ZCA26W             |                    |                     | 38                |
|                       |                    | TOTAL               | 27,461            |