

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4012	DATE	March 30,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for passenger side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012	701
DBA-CV2W		2011~2012	5,585
DBA-CV4W		2010~2011	8,110
DBA-CV5W		2010~2012	29,580
DBA-V83W	「PAJERO」	2010~2012	539
CBA-V87W		2010~2011	111
ADC-V88W		2010	44
LDA-V88W		2010~2012	552
DBA-V93W		2010~2012	2,280
CBA-V97W		2010~2012	343
ADC-V98W		2010	271
LDA-V98W		2010~2012	4,244
CBA-HA1W		「i」	2012
DBA-HA1W	2012		2,218
ZAA-HA3W	「i-MiEV」	2012	3,369
		TOTAL	58,562