

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2462	DATE	March 24 <sup>th</sup> ,2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the universal joint of the front propeller shaft, the contact surface between the spider and seal may not be in specification. In very rare cases, water and/or dirt may enter the universal joint and, over time, lead to corrosion resulting in noise or vibration. After prolonged driving under such conditions, the universal joint may eventually break. In this case, drive torque may no longer be transmitted to the front wheels.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZV30	「BMW X5 xDrive 35i」	2010 – 2013	188
DBA-ZV30S			851
LDA-ZW30	「BMW X5 xDrive 35d」	2011 - 2013	92
LDA-ZW30S			1,055
ABA-ZV44	「BMW X5 xDrive 50i」	2010 - 2013	58
ABA-ZV44S			12
DBA-FG35	「BMW X6 xDrive 35i」	2010 - 2013	628
ABA-FG44	「BMW X6 xDrive 50i」	2010 - 2013	81
AAA-FH44	「BMW ActiveHybrid X6」	2010 – 2011	34
ABA-GY44	「BMW X5 M」	2010 - 2013	61
ABA-GZ44	「BMW X6 M」	2010 - 2013	97
		TOTAL	3,157