

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4013	DATE	March 16, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the headlight, due to inappropriate programming of automatic headlight leveling system depending on the vehicle posture, the headlight optical axis may not be auto-adjusted correctly when the vehicle is inclined backwards, such as when all the seats are occupied by passengers. Therefore, the headlight beam aiming direction may be too high and may cause glare for oncoming vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KF2P	Mazda「CX-5」	2016-2017	2,683
DBA-KF5P		2016-2017	679
DBA-KFEP		2016-2017	411
		Total	3,773