

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 0 0 4	DATE	Mar.16.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the power steering oil pressure hose, due to an inappropriate clinching for the rubber hose and the mouth fitting, if the oil pressure becomes higher by repetition of steering operation, the hose might come off. Therefore, the power steering oil leaks and steering force becomes heavier, in an extreme case, the scattered oil attaches to an exhaust manifold and a thermal event may be observed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-PNZ 5 1	MURANO	2 0 1 3 ~ 2 0 1 4	1 1 3
		TOTAL	1 1 3