

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4000	DATE	Mar 13, 2017
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate programming of On-board self-diagnosis system (OBD) in Engine Control Module (ECM), it may not detect the engine failure when malfunction occurs in the intake sensor circuit and malfunction indicator light may not activate Therefore above phenomenon will not conform to the safety standards in Japan.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-VP55B	SV650	2016	980
		TOTAL	980