VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4010	DATE	Mar 3, 2017	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Since tightening of bolts and nuts which fix front strut and steering knuckle was not proper, the nut might not have been tightened by specified torque. Therefore, if car is driven in that condition, a steering knuckle could be disengaged from strut, in worst case, it becomes impossible to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA36S	ALTO		23
HBD-HA36V	ALIO		5
DBA-HE33S	ALTO LAPIN		16
DBA-MH34S		2016~2017	9
DAA-MH44S	WAGON R		8
DAA-MH55S			6
DBA-HB36S	CAROL		2
		TOTAL	69