

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4027	DATE	April 14, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the vehicles equipped with the optional accessory LED fog lamp, due to inappropriate harness, the electric circuit may not flow to the right side of the head lamp and side marker lamp and these lamps may not illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DJ3AS	Mazda 「Demio」	2016-2017	14
DBA-DJ3FS		2016-2017	62
LDA-DJ5AS		2016-2017	8
LDA-DJ5FS		2016-2017	13
		Total	97

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NUMBER	SHIPMENT YEAR	NUMBER OF PARTS
optional accessory LED fog lamp mounting kit	D23N-V7-235	2015-2016	4