

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>4021</b>	<b>DATE</b>	<b>Apr 13, 2017</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>On gas-filled back door balancers, corrosion might be generated at outer tube because of improper paint on end cap of outer tube.</p> <p>Therefore, if the vehicle is driven continuously in this condition, outer tube could be broken due to pressure of filled gas by progress of corrosion, in worst case, it could cause injury on nearby people when opening the back door.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
<b>DBA-HE22S</b>	<b>ALTO LAPIN</b>	<b>2008~2015</b>	<b>253,041</b>
<b>CBA-HE22S</b>		<b>2008~2010</b>	<b>3,725</b>
<b>DBA-MA15S</b>	<b>SOLIO</b>	<b>2010~2015</b>	<b>159,743</b>
<b>DBA-MA26S</b>		<b>2015~2016</b>	<b>2,504</b>
<b>DAA-MA36S</b>			<b>28,015</b>
<b>DAA-MA46S</b>		<b>2015</b>	<b>30</b>
<b>DAA-FF21S</b>	<b>IGNIS</b>	<b>2016</b>	<b>5,137</b>

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MB15S	DELICA D:2	2011~2015	43,257
DAA-MB36S		2015~2016	4,313
		TOTAL	499,765