

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4033	DATE	April 13,2017
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	The high-mount stop lamp is not capable of resisting its expansion and contraction by temperature changes due to its improper structure, possibly causing cracks at the welding section of the lamp. Rain water might come into such a lamp over time and, in the worst case, the lamp might not go on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA400K	COPEN	2014-2017	19,512
		TOTAL	19,512