

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4037	DATE	Apr.12.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>On an initiator in the air bag inflator of front seat driver and passenger side airbag assemblies, due to an improper trouble shooting program of the manufacturing process, there is a possibility that some initiators are manufactured with an incorrect generant mix ratio. This could result in a non-deployment of the seat side airbag under certain conditions in which it is designed to deploy.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRT272W	[AVENSIS]	2016-2017	27
		TOTAL	27