

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4031	DATE	10 April 2017
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Direction change shift lever rod is assembled opposite side and that makes it too close to the cabin frame. Therefore the shift lever may stuck when shifting to reverse position and lead the machine continue to move reverse.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-C425	「ER467」	10003~12035	653
	「ER456」	20002~21569	195
		TOTAL	848