

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4022	DATE	April 6, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the vehicles equipped with the valuable light distribution type of headlamp, due to inappropriate resin processing for actuator device adjusting the optical axis, some actuator devices may be short of strength. Therefore, continued to use, the actuator device may be broken and the optical axis of headlamp may deviate downward and the headlamp cannot illuminate the forward area adequately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KE2FW	Mazda 「CX-5」	2015-2016	6,826
LDA-KE2AW		2015-2016	6,166
DBA-KE5FW		2015-2016	843
DBA-KE5AW		2015-2016	698
DBA-KEEFW		2015-2016	1,732
		Total	16,265

THE SUBJECT COVERAGE OF VEHICLE POSSIBLY REPLACED WITH REPAIR PART

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KE2FW	Mazda 「CX-5」	2014-2015	602
LDA-KE2AW		2014-2015	522
DBA-KE5FW		2014-2015	36
DBA-KE5AW		2014-2015	34
DBA-KEEFW		2014-2015	85
		Total	1,279

THE CASE OF IMPOSSIBLE TO IDENTIFY VEHICLES REPLACED WITH REPAIR PART

NAME OF THE SUBJECT PART	PART No.	SHIPPING PERIOD OF THE SUBJECT PART	NUMBER OF THE SUBJECT PART	REMARK
Headlamp unit	K071-51031 K071-51041	NOVEMBER, 2015 -SEPTEMBER, 2016	1,162 units	