

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2467	DATE	04.06.2017
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF  DEFECT	<p>SAFETY RECALL: Certain 2014 Model Year Explorer vehicles - Explorer Rear Suspension Toe Link Replacement</p> <p>In some of the affected vehicles, the rear suspension toe link(s) may have poor weld quality, which may cause them to fracture. A fractured rear suspension toe link may cause a loss of steering control, a difficult steering condition, or rear suspension noise. Loss of steering control increases the risk of a crash.</p> <p>Dealers are to replace both rear suspension toe links, check alignment and, if necessary, adjust rear toe. This service must be performed on all affected vehicles at no charge to the vehicle owner.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1FMHK9	Explorer 2.0L FWD	2014	551 units
ABA-1FMHK8	Explorer 3.5L AWD	2014	166 units
		TOTAL	717 units