VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

$\frac{\text{Domestie}}{\text{Import Vehicles}}$

CAMPAIGN No.	GAI-2472	DATE	April 6, 2017	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	Regarding the brake pedal equipped on heavy-duty trucks, due to the inappropriate assembly of a split pin which fixes the pedal shaft to the pedal plate, the split pin may detach from the shaft during foot-brake operation. If the vehicle continues operation under these conditions, the brake shaft may slide off from the connecting part of the brake pedal and the plate and in the worst case scenario, the braking performance may be reduced.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-H2TDA1	FH	2014-2015	87
QKG-H2TEA1		2014-2015	90
-H2TEA1-		2015	6
Unspecified		2014-2015	214
		TOTAL	397