

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4045	DATE	June 1, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	<p>On the fuel pump, due to insufficient durable performance of the pump pipe, the fuel pump pipe may deteriorate by the pressure of the fuel which flows in the pipe and the heat from the engine and exhaust pipe, the pipe may be deteriorated. Therefore, continuous use may progress the deterioration of the pipe, the pipe may be cracked, and fuel leakage may be occurred, in the worst case, resulting in a fire.</p> <p>On the front suspension, due to inappropriate manufacturing process of lower arm ball joint, some ball joint socket areas may be potentially cracked. Therefore, if a large force applies to the case during driving, the ball joint may separate from the ball joint socket, in the worst case, the vehicle may become unable to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-SE3P ABA-SE3P	Mazda「RX-8」	2003-2008 2003-2004	29,902 12,984
		Total	29,902