

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	4053	DATE	Jun. 1.2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy-duty sightseeing buses, due to inappropriate joint construction of the air conditioning cover and the roof, the fastener made of resin tightening the cover may be detached, causing the cover to become loose and making the gap between the roof and the cover if the strong wind is blown from the back of the roof. If the even stronger wind is blown from the side, the cover may be damaged and drop, resulting it to disturb the traffic in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU1ESAA PKG-RU1ESAA	[HINO SELEGA]	2005~2008	1,694
BJG-RU1ASAR		2008	5
ADG-RU8JHAA BDG-RU8JHAA		2006~2008	288
		TOTAL	1,987