

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4063	DATE	15 June, 2017
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the manufacturing process of medium duty truck fuel tanks, the radius corner of the fuel tank may not be welded properly due to improper pressure settings for seam welding the corner, conducted after the press molding process. If the vehicle is operated under these conditions, fuel may exude through the corners, and in the worst case scenario, fuel may drip out through the corner.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-MK38L	UD Trucks Condor	2017	1
QKG-PK39CH	UD Trucks Condor	2017	1
QKG-PK39LD	UD Trucks Condor	2017	1
TOTAL			3

The vehicles may have the concerned parts equipped as service parts.

TYPE	COMMERCIAL NAME	PARTS DELIVERY YEAR	NUMBER OF VEHICLE
BDG-LK36C	Nissan Diesel Condor	2017	1
KK-MK252FB	Nissan Diesel Condor	2017	1
KK-MK25A	Nissan Diesel Condor	2017	2
KK-MK262GB	Nissan Diesel Condor	2017	1
KK-MK26A	Nissan Diesel Condor	2017	1
PB-MK36A	Nissan Diesel Condor	2017	1
BDG-MK36C	Nissan Diesel Condor	2017	3
PK-PK36A	Nissan Diesel Condor	2017	1
BDG-PK37C	Nissan Diesel Condor	2017	1
U-RM210GSN	Nissan Diesel -	2017	1
QKG-PK39LD	UD Trucks Condor	2017	1
TOTAL			14