

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4061	DATE	June 16,2017
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	There is a potential that low brake volume alarm may be reported due to the brake oil leakage into the axle assembly. This is caused by an incorrect oil seal, which is to prevent oil leakage from brake system to axle, assembled to the brake piston. If the machine is kept used in this condition, the braking performance will decrease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-50C4	「50ZV-2」	2013	2
KDP-A4SDT30	「4SDT30」	2013	1
EDR-65J4	「65ZV-2」	2013	12
TOTAL			15