

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4075	DATE	June 23,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	The oil passage in the cylinder block of the engine may not completely pass through due to abnormal casting process of the cylinder block in which the core of the mold had been placed improperly. As a result, the journal metal of the crank shaft may burn out causing abnormal noise due to lack of oil supply. In the worst case, the engine may burn out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B11W	「eK」	2017	1
		TOTAL	1