

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2505	DATE	Jun 29, 2017
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	Harley-Davidson has learned that the oil line clamp used on the oil cooling system on certain model year 2017 Touring model motorcycles built in the US 03/08/16 through 05/09/17 may not have been properly installed, such that an oil line may become detached and cause a sudden loss of engine oil. If this condition remains undetected it could lead to oil on the rear tire which may result in loss of vehicle control, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FLC	STREET GLIDE SPECIAL	2017	551
	ROAD GLIDE SPECIAL	2017	288
	ROAD KING	2017	74
	ROAD KING SPECIAL	2017	181
KRC	STREET GLIDE SPECIAL	2017	2
KTC	ROAD GLIDE SPECIAL	2017	2
FBC	ROAD KING	2017	2
		TOTAL	1100