

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4069	DATE	June 29 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>The subject matter relates to the brake relay valve installed on the heavy-duty tractors. Because a pressure sensor used to measure brake pressure was manufactured improperly, some IC chips came off from the sensor circuit boards. If continued to use without replacement, the sensor will not measure brake pressure correctly, or in the worst case the brake forces of the right and left rear wheels may vary and this may result in reduced driving stability.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-EXD52BD	[GIGA]	2016	130
QKG-EXD52BE		2016	49
QKG-EXD52BG		2016	7
QPG-EXD77BD		2016	9
QPG-EXD77BG		2016	3
QDG-EXY52BJ QKG-EXY52BJ		2016	5
QDG-EXZ52BJ		2016	30
		TOTAL	233