

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4079	DATE	July 10 , 2017
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	Some bulb mounting clasps for tail/break lamp were installed improperly in the socket. It may cause removing clasps from the socket by vibration during running resulting the bulb falling down and tail/break lamp going out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BK-LE250D	Versys-X 250 ABS	2017	453	
	Versys-X 250 ABS Tourer	2017	358	
			TOTAL	811