VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4065	DATE	JUL-14-2017	
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao			
SUMMARY OF DEFECT	As for front wiper, due to improper tightening on wiper arm fixture nut on wiper motor drive shaft, the nut may be loosen during wiper operation, because of low tightening torque. As a result, continuing operation with this condition may lead worn on loosen coupling portion (serration) and this may make the motor drive shaft turn free, in the worst case, front wiper may not work at all.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDN-S1091A	KIORITZ SPEED SPRAYER SSV1091 F SC	2016~2017	48
		TOTAL	48