

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4081	DATE	July 20,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the front wiper motor, the inside of the motor may corrode in the event that the water dropped down through the gap between the front deck garnish and the windshield glass intrudes into the inside the motor due to inappropriate water proof structure of the front deck. In the worst case, the wiper motor may stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-CW4W	「OUTLANDER」	2010~2012	4,547
		2009~2010	2,910
DBA-CW5W		2005~2012	36,510
		2007~2010	25,294
DBA-CW6W		2009	1,868
		2007~2009	2,007
		2009	99
		TOTAL	73,235