

Vehicle Safety/Pollution Recall Campaign In Japan

Domestic/Import Vehicles

Campaign No.	Gai 2507	Date	J u l y 2 1 , 2 0 1 7
Name(s) of person or company	Tesla Motors Netherland BV Managing Director : Todd Andrew Maron Director of Homologation : Suraj Nagaraj Country : United states Manufacturer : Tesla Motors, Inc. Phone number: 0120-975-214		
Condition of structure and system acknowledged as non-compliant condition, and its root cause	Some of Electric parking brakes installed on vehicles may contain a small gear that could have been manufactured improperly by our supplier. If this gear were to break, the parking brake would continue to keep the car from moving, but In worst case the parking brake would then be stuck in place		
Details of countermeasure	Replace both rear parking brake calipers to Good products.		
Distribution method to owners and 3 rd party dealerships	<ul style="list-style-type: none"> • Current Owners : notify by email or phone call • 3rd party dealerships : Post to "Nisei-ren kikanshi" • Tracking method : Apply a sticker (Gai 2507) to the area below the door striker of the front passenger side • Tracking method : Apply paint on door striker of the front passenger side 		

Make	Type	Commercial Name	Affected VIN and imported period	Number of affected vehicles	Note
Tesla	NA	Model X	5YJXDCE28GF017123 ~ 5YJXDCE26GF017122 H28, 10/6 ~ H29, 4/27	2	Standard
	NA	Model S	5YJSB7E28GF130495 ~ 5YJSB7E29GF162565 H28, 4/11 ~ H28, 11/5	147	Standard
	NA	Model S	5YJSB7E47GF130778 ~ 5YJSB7E46GF155641 H28, 4/11 ~ H28, 9/26	35	Performance
	Total (1Type)	Total (2Model)	(Imported Period) H28, 4/11 ~ H29, 4/27	Total (184)	