

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4090	DATE	Aug 4,2017
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some wheel cranes there are cases of the engine compression release brake failing to operate properly due to the engine control unit (ECM) transmitting the wrong signal in the signal circuit for operating the engine compression brake release. With continued use of the vehicle in this condition there is a risk of decreased engine output, or discharge of white smoke exhaust and, in worst cases, engine failure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-T013	TADANO 「GR-700N-2」	2016 ~ 2017	75
YDS-EG05	KOBELCO 「RK700-3」	2017	3
		TOTAL	78