

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4099	DATE	August 24 ,2017
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the flat bed semi-trailer with coil pocket, strength of coil pocket part (trailer bed) is insufficient. Therefore, a fissure occurs on the steel plate of coil pocket because of loading stress of the large coil		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PFV335AB	—	2013~2014	5
PFV335AD	—	2014	12
PFV335AE	—	2014	3
PFV335AF	—	2014	2
PFV335AG	—	2015	1
PFV335AH	—	2015	13
		TOTAL	36