

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4097	DATE	Aug.31.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the driver or front passenger air bag assembly of the subject vehicles, due to improper work operation at the vehicle assembly plant, there is a possibility that the air bag assemblies with different specification may have been installed in some vehicles. In this condition, the airbag may not inflate properly during deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
CBA-UZJ200W	[LAND CRUISER]	2007	1	Driver side
TA-NZE121	[COROLLA]	2002	1	
CBA-UZJ200W	[LAND CRUISER]	2007, 2008	2	Front Passenger side
CBA-URJ202W		2012 - 2016	4	
DBA-URJ201W	[LX570]	2016	2	
DBA-NSP120X	[TREZIA]	2014	1	
TOTAL				