

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2525	DATE	7/September/2017
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	<p>In the defected part, the crimping of the tube that hold the Micro Gas Generator (MGG) in place is not up to specification. In the event of a crash where the pre-tensioner is activated and in combination with certain conditions. This might cause the pressure in the tube to be too high for the defected crimping and the MGG may detach from the tube and propelled in the direction out from the tube. Despite this condition, the seat belt works properly.</p> <p>The corrective action is to replace the right hand side seat belt in the 3rd seat row.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[VC90]	2017	292
		TOTAL	292