

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4104	DATE	19-Sep-17
MANUFACTURER	KYB Corporation 4-1, Hamamatsu-cho 2-chome, Minato-ku, Tokyo, Japan		
DESCRIPTION OF DEFECT	The control cable for operating the drum of the concrete mixer truck, since the wiring is inappropriate, the fixing clip may be deformed at the time of the cab-tilt and the control cable may contact with the air tube for the brake. Therefore, if continue to use it as it is, the air tube of the vehicle will be damaged by traveling vibration, and in the worst case there is a risk that one brake line will be lost and the braking stop distance will be extended.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-GK8JKFA	「HINO RANGER」	2005	10
PK-GK8JKFA	「HINO RANGER」	2004-2005	33
ADG-GK8JKWA	「HINO RANGER」	2005-2007	49
BDG-GK8JKWA	「HINO RANGER」	2007-2010	72
LDG-GK8JAAA	「HINO RANGER」	2012-2016	165
TOTAL			329

(日本工業規格A列4番)