

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4108	DATE	Sep 21, 2017
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>On the front wiper motor, corrosion might be generated at inside of the motor due to insufficient waterproofing.</p> <p>Therefore, if the vehicle is used continuously in this condition, corrosion level become worse, in worst case, wipers do not operate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA25S	ALTO	2009~2012	167,017
HBD-HA25V			42,163
DBA-HA35S			23,614
DBA-HB25S	CAROL		31,908
DBA-HB35S			306
			TOTAL