

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4116	DATE	September 27, 2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain engines of buses, due to the improper installation requirement of the wrist pin bushing into the connecting rod, there are some that retention of the wrist pin bushing is insufficient. Therefore, if the vehicle remains in operation with the condition, the wrist pin bushing may wear out and be damaged, causing it to make an abnormal noise, and in the worst case, the engine may be damaged, resulting the vehicle unable to move.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-RU8JHAJ	[ISUZU GALA]	2010	16
LDG-RU8JHBJ SDG-RU8JHBJ		2010-2011	15
BDG-RR7JBJ	[ISUZU GALA MIO]	2010-2011	130
		TOTAL	161

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-RU8JHAJ	[ISUZU GALA]	2008	1
BDG-RR7JBJ	[ISUZU GALA MIO]	2011	1
		TOTAL	2