

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4120	DATE	Oct.4.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the Motor Generator for generating electrical power installed in the hybrid vehicle transaxle assembly, due to inadequate crimping of the plate which holds the magnets on the motor shaft, there is a possibility that the plate could wear by long-term idling and/or high-load driving and may contact the motor coil and lead to the short circuit. If this were to occur, the warning lights would illuminate and, in the worst case, the hybrid system could shut down resulting in the vehicle stopping.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-AZK10	[SAI]	2009-2010	34,123
DAA-ANF10	[HS250h]		21,505
		TOTAL	55,628