

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4118	DATE	October 10 ,2017
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		On heavy-duty tractors with the fuel device, 'fuel tank', relocated from between the wheelbase to on the deck placed behind the cab, cracks may possibly be generated on the bracket caused by the weights of fuel tank and the vibration of travelling due to inappropriate structure of the bracket securing the fuel tank. With the above conditions, continued use of the vehicle may lead to incline the fuel tank while these cracks develop.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-EXY52AJ	"GIGA"	2010/10	1
LDG-EXY52AJ		2011/7	1
QKG-EXY52AJ		2012/4 – 2014/10	7
QKG-EXY52BJ		2016/7	1
		TOTAL	10

|