VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2546	DATE	October 18, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Due to improper software, 1) Stop lamp does not operate during emergency braking 2) Position light is activated alternating during turn signal operation 3) Improper readout the engine torque value. A software update must be carried out on the vehicles affected.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8UCULB	Q3 2.0Tq 132kw	2015 – 2017	1,453
ABA-8UCULC	Q3 2.0Tq 162kw	2015 – 2017	165
ABA-8UCZD	Q3 1.4T	2015 – 2017	1,814
ABA-8UCZGF	RSQ3	2015 – 2017	334
		Total	3,763