

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4128	DATE	Oct.18.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In an inverter of the hybrid system, due to an incorrect trouble shooting in the manufacturing process, there is a possibility that a condenser is not fixed to the inverter by fixation bolts and supported only by a terminal in some vehicles. If this were to occur, the terminal was broken by driving vibration, the warning lights would illuminate and, in the worst case, the vehicle loses motive power.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW50	[PRIUS]	2015-2016	9
DAA-ZVW51			6
DAA-ZVW55			4
DAA-ZYX10	[C-HR]	2017	1
		TOTAL	20