

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4144	DATE	December 1,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for passenger side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2013～2016	26,562
DBA-CV2W		2013～2016	5,006
DBA-CV5W		2013～2016	5,968
DBA-V83W	「PAJERO」	2013～2017	413
LDA-V88W		2013～2017	692
DBA-V93W		2013～2017	901
LDA-V98W		2013～2017	4,976
CBA-HA1W	「i」	2013	171
DBA-HA1W		2013	448
ZAA-HA4W	「i-MiEV」	2013～2016	1,687
		TOTAL	46,824