

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4152	DATE	Dec.6.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the resin fuel tank of the subject vehicles, due to improper setting for the welding machine, there is a possibility that the fuel inlet pipe could be welded with the fuel tank in a tilted condition causing a portion of the resin weld to be insufficient. In this condition, the welded surface could peel off, causing a fuel leak when the tank is full or being refueled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZWA10	[CT200h]	2016-2017	640
		TOTAL	640