

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4156	DATE	Dec.7 2017
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	With regards to the wiring harness which is connected to Heavy Duty bus generator, due to improper clamping of the power supply cable and signal lines, whilst driving the signal lines may be damaged and disconnected by vehicle's vibration. If the vehicle continues operation in this condition, the vehicle may not control power generation then the battery charge become unavailable with warning lamp on. The worst case scenario is that the vehicle might become inoperable.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-MP35UK	「FUSO AERO STAR」	2011~2014	200
PKG-MP35UM		2011~2014	732
PKG-MP35UP		2011~2014	144
PKG-AP35UK	「SPACERUNNER A」	2012~2014	22
PKG-AP35UM		2011~2014	105
PKG-AP35UP		2012~2014	20
		TOTAL	1,223