

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-2573	DATE	15 <sup>th</sup> Dec 2017
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	On affected machines there is a risk of one of the link leads to the regulator rectifier developing an electrical short. A bracket introduced at the start of production may interfere with the link lead, resulting in damage to the outer protective sheathing and over time potentially exposing the wire. Contact between the bracket and the exposed wire may lead to an electrical short. In some cases the electrical short may cause an engine stall without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-5J1050	Speed Triple S	2017-2018	13
	Speed Triple R		90
		TOTAL	103