## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN NO.	4220	DATE	March 15 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain engines of heavy duty buses, the lock nut tightening torque concerned may be insufficient because the tightening process of the intake and exhaust valve clearance adjusting lock nut is inadequate. Therefore, if it is used under the condition continually, the lock nut concerned may be loosen, come out and enter inside the engine, resulting the engine to be damaged.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2KG-RU2AHDJ	[ISUZU GALA]	2017	1
		TOTAL	1