

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4227	DATE	27/3/2018	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the lighting device for Heavy-duty trucks, due to improper crimping of wiring terminals for headlight switch, some of the contact resistance at the terminals may become increase. Thus, the terminals might have conduction failure, upon which the headlight may have a risk of becoming disable.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	Quon	2017	4	
2PG-CD5BA	Quon	2017-2018	17	
2PG-CD5BL	Quon	2017	16	
2PG-CD5CA	Quon	2017-2018	314	
2PG-CD5CL	Quon	2017-2018	22	
2PG-CG5BA	Quon	2017	3	
2PG-CG5CA	Quon	2017-2018	599	
2PG-CG5CE	Quon	2018	1	
2PG-CG5CL	Quon	2017-2018	27	
2PG-CW5AL	Quon	2017-2018	187	
2PG-CW5BL	Quon	2017-2018	41	
2PG-CW5CA	Quon	2017-2018	29	
2PG-CW5CL	Quon	2017-2018	43	
2PG-CX5BA	Quon	2017-2018	12	
2PG-CX5BL	Quon	2017	7	
2PG-GK5AAB	Quon	2017-2018	84	
2PG-GK5AAD	Quon	2017-2018	44	
2PG-GK5AAE	Quon	2017	1	
		TOTAL	1451	