

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4218	DATE	Mar . 29 , 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	「LEGACY」	2013	646
DBA-BMG		2013	865
DBA-BMM		2013	3,000
DBA-BR9		2013	16
DBA-BRF		2013	117
DBA-BRG		2013	2,696
DBA-BRM		2013	12,243
			TOTAL