

CAMPAIGN No.	4237	DATE	2018.4.6		
MANUFACTURER	HANTA MACHINERY CO. LTD.				
DESCRIPTION OF DEFECT	Due to inappropriate case pressure of HST travelling pump on travelling device, that pressure may go beyond the permissible value when starting the engine. Accordingly, if using the machine under this condition, the axle seal of HST travelling pump will wear out and oil will leak, and then there is a potential danger of inability to travel in the worst case.				

	I			
TYPE	COMMERCIAL NAME		DEL YEAR CCALLED	NUMBER OF VEHICLE
YDN-F45W5	「Asphalt Finisher」	2017~2018		49
YDN-A45WD	「Asphalt Finisher」	20	17~2018	70
			TOTAL	119