

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |   |      |              |
|-----------------------|---|------|--------------|
| CAMPAIGN No.          | 4281  | DATE | June 7, 2018 |
| MANUFACTURER          | Mazda Motor Corporation   |      |              |
| DESCRIPTION OF DEFECT | On the engine control unit with gasoline engine, due to inappropriate manufacturing process of the capacitor installed in electronic circuit to work the fuel injector, some internal parts may be broken. Therefore, in continuous use under the condition, damage on internal parts may develop and the engine may stall and not be able to restart. Also, if keeping Ignition Switch on, the fuel injector or the moving parts in the high pressure fuel pump may get overheated and the resin portion may melt, resulting in fuel leakage. In the worst case, vehicle fire may occur. |      |              |

| TYPE     | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| 6BA-KFEP | Mazda<br>「CX-5」 | 2018                | 10                |
| 6BA-KF5P |                 | 2018                | 2                 |
|          |                 | Total               | 12                |