

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 2 9 5	DATE	J u l . 1 0 . 2 0 1 8
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate shape of the collar at the drive chain guard and the swing arm fastening area, the bolts at the fastening area may get loose, caused by a vibration while running on a rough road. Therefore, if it is used in that condition continuously, the said bolts may drop and the said guard may greatly waggle causing it to contact the drive chain. In the worst case scenario, the said guard may get broken and drop on the road, and as a result, it may interfere with traffic flow.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B L - R M 2 2 J	X S R 7 0 0	2 0 1 7	7 4 8
2 B L - R M 1 9 J	M T - 0 7 A	2 0 1 8	2 2 0
		TOTAL	9 6 8