## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	4305	DATE	2018/8/3		
MANUFACTURE	Niigata Transys co.ltd.				
DESCRIPTION OF					
DEFECT					
	In a fuel pump of a rotary snowplow, because structure of the motor brush is inappropriate, the brush may be abnormally worn and contact failure. Therefore, the fuel pump malfunctions, and in the worst case, the engine stops during running and it can not restart.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
WDP-NR3B	NR83	2014~2017	87	
YDR-NR3C	NR84	2017~2018	18	
WDP-NR3B改	NR103T	2014~2017	13	
YDR-NR3C改	NR104T	2017~2017	5	
WDR-NR4B	NR143	2014~2017	37	
YDR-NR3C	NR144	2017~2017	5	