

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4329	DATE	August. 31. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain sampling inspection engines for light duty trucks, due to the improper fixing method of the exhaust emissions inspection equipment and an exhaust pipe, bending stress which doesn't occur in installing in a vehicle may be applied to the pipe, causing cracks in the welded part of the pipe. Therefore, exhaust emissions and DPR (Diesel Particulate active Reduction) regeneration fuel may leak from the crack part.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZU700M 2KG-XZU700X	[HINO Dutro]	2017~2018	12
2KG-XZU710M		2017	2
2KG-XZU720M		2017~2018	7
2KG-XZU730M		2017~2018	3
		TOTAL	24