VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4361	DATE	Nov. 01, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to improper design, combination of an excessive stress compared to the design condition and micro foreign matter in the valve spring material within the general manufacturing dispersion, may cause the spring to fracture. If the spring fractures, abnormal engine noise or engine malfunction may occur, and in the worst case, the engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJ6	「IMPREZA」	2012~2013	2,031
DBA-GJ7		2012~2013	7,177
DBA-GP6		2012~2013	5,295
DBA-GP7		2012~2013	33,062
DBA-SHJ	「FORESTER」	2012	4,739
DBA-SJ5		2012~2013	14,242
DBA-ZC6	「BRZ」	2012~2013	7,803
DBA-ZN6	「86」	2012~2013	26,804
		TOTAL	101,153